






Certificate of Reoccupation				16BT/A/GW/838			
Site Address	St Marks Primary School, Lower Boston Road, Hanwell, W7 2NR						
Client Name & Address	Omega Environmental, Suite 1, Pirton Grange, Pirton Road, Shillington, SG5 3HB			Customer Order			
Areas and description of work	Removal of Insulation debris to a section of the boiler house wall						
Name and address of asbestos removal contractor	Same as client						
Responsible site person	Jamie Toms		Report Generated by REC	Bishops Stortford			
Company if different from Contractor							
Stage 1 of 4: Preliminary Check of Site Condition and Job Completeness							
Plan of work checked?	Yes	Comment					
Are the following intact / satisfactory?	Work area?	Yes	Enclosure / NPU ?	Yes	Hygiene facilities ?	Yes	
Are the following free from debris, ACMs, sacks and waste?	Surrounding area ?	Yes	Waste route /skip area	Yes	Transit Route?	Yes	
Waste Disposal Method	Waste Van n						
Stage 1:	Time: 08:35	Date: 22/07/16	Sign:				
PASS	Assessed by:	Gavin Warwick					
Stage 1 checks were all satisfactory, proceed with Stage 2							
Stage 1 Comments:							
Stage 2 of 4: Visual Inspection							
Requirement			Comments				
Hygiene unit free from waste, debris, dust, contaminated clothing & dry.		Yes					
Airlock/enclosure are free of waste bags, materials and unnecessary equip'		Yes					
All ACMs have been completely removed from the underlying surfaces		Yes					
Interior surfaces inside the enclosure are free from dust, debris and dry.		Yes					
Time taken for visual assessment		25	Minutes				
Stage 2:	Time: 09:10	Date: 22/07/16	Sign:				
PASS	Assessed by:	Gavin Warwick					
The hygiene unit, air lock and enclosure were FREE from visible asbestos waste and surface dust, proceed with Stage 3							
AIB present in the pipe penetration in wall but not accessible, contractor to seal with expanding foam							
Stage 3 of 4: Clearance Air Monitoring Inside the Enclosure							
Sampling Information	Yes	Comments / Values					
All areas dry?	Yes						
Air movers off and sealed?	Yes						
No evidence of lock down sprays?	Yes	Time of Disturbance	1.5	Minutes			
Disturbance used (State type)	Brushing	Enclosure volume (m3)	8				
Number of pumps used in areas	1	DCU Tested?	Yes				
Dead spots identified - Describe							
Results (full fibre count details are contained within the associated air monitoring certificate)	Satisfactory. All results were below the HSE clearance indicator of 0.010 f/cm3.						
Sign Stage 3:	Time: 09:55	Date: 22/07/16	Sign:				
PASS	Assessed by:	Yes					
The enclosure can now be removed and Stage 4 conducted							
Stage 3 Comments:							

Stage 4 of 4: Assessment of Site for Reoccupation (after enclosure removal)		
Requirements		Comments
Work / former enclosure area is free from visible debris, asbestos sacks & waste?	Yes	
Transit route and waste area is free from any asbestos debris, sacks and waste?	Yes	
Have all ACMs specified in the plan of work been removed?	Yes	
Sign Stage 4:	Time: 10:20	Date: 22/07/16
PASS	Assessed by: Gavin Warwick	Sign: 
The area can now be reoccupied		
Stage 4 Comments:		
Clearance Monitoring of the Hygiene Unit		
Hygiene Unit	151RT1702	has passed a visual assessment and air monitoring and is cleared to leave this site. Please see associated Hygiene Unit Inspection Certificate and Air Monitoring Certificate for further details.
Comments:		
Acknowledgement of Receipt of Certificate		
Site: St Marks Primary School, Lower Boston Road, Hanwell, W7 2NR		
Certificate accepted?	Yes / No (circle / delete)	Date 22/07/16
Comments:		
SIGN:		PRINT NAME: Jamie Toms

End of Certificate

REC Stansted

Environment House, Bullocks Lane, Takeley, Bishop's Stortford Herts, CM22 6TA
T. 01279 879 416 F. 01279 879 414

REC East Kilbride

16 Langlands Place, Kelvin South Business Park, East Kilbride, Glasgow, G75 0YF
T. 01355 573360 F. 01355 573351

REC Manchester

Osprey House, Pacific Quay, Broadway, Manchester, M50 2UE
T. 0161 868 1300 F. 0161 868 1301

REC Omagh

Unit A5, Omagh Business Complex, 41 Gortrush Ind Estate, Omagh, BT78 5LU
T. 028 8225 3378

REC Plymouth

Unit 13, Barn Close, Langage Business Park, Plymouth, PL7 5HQ
T. 01752 347789 F. 01752 347749